






Product Obsolescence Statement

After many years service the 8100 & 8200 Monitors have ceased manufacture. They have been replaced by the 8200w² Monitor.

We will continue to offer repairs and servicing on the old products for as long as reasonably possible, this is planned for 5 years unless circumstances out of our control prevent us.

Technical support will continue for these products for as long as our customers need it.

Old		Current
8100 Monitor		8200w ² Monitor
8200 Monitor		
IR100		SoliTechw ² IR 0-200
IR40		SoliTechw ² IR 0-1,500
IR15		SoliTechw ² IR 0-10,000
IR8		SoliTechw ² IR 0-30,000

You will need a SoliTechw² IR Sensor for use with the 8200w² Monitor. A range of upgrade pricing arrangements have been put in place on a customer by customer basis, if you have any concerns please talk to your normal Partech sales contact.

The IR100, IR40, IR15, IR8 will continue to be available as replacement parts.



Angus Fosten



Roger Henderson

Joint Managing Directors